ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
11

Ward Name
Kuvempu Nagar

Street ID
W0075, W0024, W0091, W0085, W0097, W0093, W0087, W

Street Name
NA, Om Shakthi Lyt 3rd Crs, 16th Crs, 15th Crs

Significant Landmark
Singapura Paradise road

Segment No.
11/C-W0075/S031520

Total Length (m)
549.96

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	37.27	77.542761	13.084347	77.542756	13.084684	W0097	W0018
2	138.88	77.542024	13.084373	77.543300	13.084269	W0065	W0095
3	158.15	77.541992	13.083982	77.543445	13.083861	W0065	W0097
4	106.63	77.542609	13.082916	77.542684	13.083877	W0034	W0024
5	109.03	77.542228	13.082932	77.542314	13.083914	W0034	W0024

Work Details

History of Road / Lane / Circles

Name of the Work
Road Development and asphalting work at Singapura Paradise road in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
1999000

Sanctioned Year
2015

Year
2015 - 2016

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Road Development and asphalting work at Singapura Paradise road in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone

Job No. / Work Code
011-15-000042

Work Order No.
EE/BTP/BBMP/E-PMT/57/2015-16

Work Order Date
29/04/2015

Period of Extention
60 DAYS

Defect Liability Period From
30/07/2015

Defect Liability Period To
29/07/2016

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
N KEERTHI		0.00
Phone No.	**E-Mail ID**	
9731567144		

Field Inspection Details

Number of Trees	Any Other Information	Name
6		RANGANATH
Date of Inspection	**Remarks**	
18/03/2017	COMPLETED	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone:	YELAHANKA	Ward No:	11	Ward Name:	Kuvempu Nagar	Street ID:	W0075, W0024, W0091, W0085,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	19/03/2017	17/04/2017	COMPLETED
SE	VASU K M	19/03/2017	17/04/2017	COMPLETED
EE	VASU K M	18/03/2017	17/04/2017	COMPLETED
AEE	MAHADEV	18/03/2017	17/04/2017	COMPLETED
AE	RANGANATH	18/03/2017	17/04/2017	COMPLETED
AE	RANGANATH	18/03/2017	17/04/2017	COMPLETED